## TO WHOM SO EVER IT MAY CONCERN BUILDING SAFETY CERTIFICATE

Shamshi Tehsil Bhunter Distt. Kullu HP has been inspected by the Assistant Engineer Bhunter Sub Division HPPWD Bhunter. As per his visual inspection the building seems to be safe to run school classes for the academic year 2023-24 under normal condition. However structural stability cannot be ascertained due to non availability of structural design, drawings and IS specification required for the building construction. This certificate is being issued purely on the basis of visual inspection and issuance of this certificate does not confer any legal and financial liabilities on the issuer. Further no addition & alteration be carried out in the building and if any addition & alteration is required fresh safety certificate be obtained.

Executive Engineer, Kullu Division, HPPWD Kullu,

No.PW/KD/WA-I/Building/2023 2323-24

Dated: 12-5-23

Copy to the Assistant Engineer Bhunter Sub Division HPPWD Bhunter with reference to his office letter No. PW/BSD/Bldg. Safety Certificate/2023-104 dated 12.5.2023 for information and necessary action.

Copy to the Principal Holy Angels School V.P.O

Shamshi Tehsil Bhunter Distt. Kullu HP

Executive Engineer, Kullu Division, HPPWD Kullu.

Askutish Manager Hoty Angels School

Kullu(H,p)

Principal

Holy Angels School

Shamshi Distt. Kullu (HP.)